

INST #14

ATTENTION!! This comp **MUST** be pilot reamed for alignment! It may be necessary to pilot ream again after 1500 rounds!

EGW Alignment reamer 375 or larger for the .38 caliber is highly recommended.

Break all sharp edges on top of ports to prevent comp from breaking.

Please have a qualified gunsmith install this part!!